



Front View of the Home



Remove forms



"X" brace all lateral bracing



Install insulation over all recessed lights



Loose and twisted gusset plate



Loose gusset plate



Missing/poorly installed insulation at coffer ceilings



Install lateral bracing across these trusses at the wall line



Install 2x4 under the rafters for support



Install insulation box over the pull down stairs



Note the missing cement under the tub




Loose handle in master bath shower



Area of shower and master bath that is wet behind the tile



Align all doors and drawers on cabinets with full overlay doors



Extend this tread to the wall



Warped door in home office



Gusset plate on truss barely securing the lower web



Install fillets on all I-beams with hangers as per manufacturer's recommendations

Inspections, Plus



Double/replace this damaged I-beam




Buckled shingles



Mulch to close to framing/home



Missing shutter



Soffit area to check for loose/debris.



Several areas of the home have this condition



Short soffit noted in rear of home